



### **Tap Geometries**



**I6** Flute length

Sqaure dimension


### **Tap Centering**




### **Tap Construction dimensions**

Gewindebohrer / Tap	DIN 352	DIN 2181	DIN 5157	DIN 40432	
Gewindebohrer / Tap	DIN 371	DIN 40435			
Gewindebohrer / Tap	DIN 376	DIN 374	DIN 5156	DIN 40433	DIN 40435
Gewindeformer / Forming Tap	DIN 2174	DIN 371			
Gewindeformer / Forming Tap	DIN2174	DIN 376	DIN 2189		

#### **Tap Chamfer Forms**



#### Form A long, 6 - 8 thread straight flutes for short through holes



**Form B** medium, 3,5 - 5,5 threads straight flutes with spiral point for through holes in medium- and long chipping materials

2-3 x P

**Form C** short, 2 - 3 threads straight and spiral flutes for blind holes in medium- and long chipping materials for through holes in short chipping materials

3,5-5 x P



**Form D** medium, 3,5 - 5 threads straight and spiral flutes 15° for blind holes with long thread runout for short through holes

1,5-2 x P

 Form E very short, 1,5 - 2 threads straight and spiral flutes 15° for blind holes with short thread runout



Form F very short, 1 - 1,5 threads straight and spiral flutes for blind holes with short thread runout Avoid if possible.

#### Please note:

Short chamfers cut threads close to the bottom of the borehole. Long chamfers reduce the forced on the cutting edges (recommended for materials with higher material strength) Long chamfers increase the required torque.

М	MF	G	UNC	UNF	UNS	UNEF	8	12	BSW	BSF	TR	NPT	NPS	RC	BA	W	PG	FG	RD	MINI	Camera	VG	Tools	Techn.
		(BSP)					UN	UN				NPTF	NPSM	RP				BSC	RMS		(Tripod)			Information



#### **Tap flutes**



Form A, C, E straight-fluted for through and blind holes


The flutes can hold a part of the chips. Chips get only partically removed in cutting direction. For this reason it is not recommended to use the tap for deep holes.



#### Form B


straight-fluted with spiral point for through holes

Due to the spiral point the chips are getting removed tightly rolled in cutting direction and prevents chip-packing. Coolant-lubricant can flow freely.




Form C, D 8 - 15° left-hand spiral flutes for through holes

Due to the left-hand spiral flutes the rake angle remains constant and ensure stable chamfer teeth to produce threads in high-strength materials. The left-hand spiral flutes forces the chips to remove ahead of the tap.




Form C, E 10 - 15° right-hand spiral flutes for blind holes

Especially suitable for automatic lathes and multi-spindle machines. Due to the chip removal against the cutting direction a secured tapping process is assured in hard conditions, even for threads with cross holes.







Due to the high spiral flutes, the chips can be removed securely also in long-chipping and deep blind holes.












### Tolerances



Flankendurchmesser-Toleranz des Innengewindes nach DIN ISO 965-1 Pitch diameter tolerance of internal thread acc. DIN ISO 965-1

Gewindebohrer mit spezieller Flankendurchmesser-Toleranz Taps with specific pitch diameter tolerance

Flankendurchmesser-Toleranz des Gewindebohrers nach DIN EN 22857 Pitch diameter tolerance of the tap acc. DIN EN 22857

Flankendurchmesser-Toleranz des Ausschusslehrdorns nach DIN ISO 1502 Pitch diameter tolerance of the no-go thread plug gauge acc. DIN ISO 1502

Flankendurchmesser-Toleranz des Gutlehrdorns nach DIN ISO 1502 Pitch diameter tolerance of the go thread plug gauge acc. DIN ISO 1502 EI = Grundmaß

Basis

t = Toleranzklasse 5 des Innengewindes (Toleranzeinheit)
 Tolerance class of the internal thread (tolerance unit)

TD2 = Toleranz des Flankendurchmessers Pitch diameter tolerance

tolerance cla	ss of tap	tolera	nce fie	eld inte	ernal th	nread	remarks	Applications
4H (DIN 802/1)	ISO 1	4H	5H				undersize	Threads with small clearance
6H (DIN 802/1)	ISO 2	4G	5G	6H			normal	Thread with normal clearance
6G (DIN 802/1)	ISO 3			6G	7H	8H	oversize	Threads with large clearance
7G (DIN 802/4)					7G	8G	oversize	before heat treatment, causing distortion
6H +0,1							oversize	Electroplating allowance ≈ 25µm thickness
6H +0,2							oversize	Electroplating allowance ≈ 50µm thickness



### **Tap Surface Treatments**




#### **Coating services**

Every threading tool of our product range - whether or not cataloged - can be delivered with any coating or surface treatment in short time.

### Troubleshooting guide for tapping

Tapping undersized threads	Pitch error Too small tolerance Geometry of the tap is not suitable for the material
Tapping oversized threads	Cutting speed is too high Bad running accuracy Chip jammings in flutes Incorrect positioning of workpiece or tap Inconsistent feed of tap Too high tolerance
Poor thread surface	Cutting speed not suitable Cooling is not suitalbe or not existing Geometry of the tap is not suitable for the material Core hole too small
Thread break of the thread to be cut	Geometry of the tap is not suitable for the material Core hole too small Core hole not deep enough Chip jammings in flutes Bad running accuracy Incorrect positioning of workpiece or tap Inconsistent feed of tap
Low tap lifetime	Cutting speed not suitable Cooling is not suitable or not existing Geometry of the tap is not suitable for the material Surface treatment/ coating for tap needed Core hole too small
Tool outbreaks	Geometry of the tap is not suitable for the material Core hole too small Core hole not deep enough Chip jammings in flutes Bad running accuracy Incorrect positioning of workpiece or tap Inconsistent feed of tap Worn tap
Cold welding on the tap	Cutting speed not suitable Increase coolant supply



### **Tap Cutting speeds**

The cutting speeds for taps depend on following parameters:

- material of the workpiece
- tap geometries
- lubrication
- and more.

You can fin the cutting speed in the product describtions of the taps in our online-shop. Just enter the item number into the Search-field and find the cutting speeds in the bottom part of the product describtion.

### Lubrication and cooling

It is recommended to use one of the following coolings or lubrications to improve the thread results andtool life time.

#### Dry machining and pressurized air

- cast iron
- (Cooled) pressurized air is used for chip removal

#### Emulsion

- Most common coolant-lubricant for thread cutting

#### Thread cutting oil

- Achieving excellent thread surfaces and tool life time

#### Thread cutting paste

- suitable for forming taps
- good results with horizontal cutting direction
- for bigger diameters and through holes

#### MQL - Minimum-quantity lubrication

- cooling by aerosol



### Formula

Describtion	Symbol	Unit	Formula	Example
Rotation speed	n	min <sup>-1</sup>		
Angular speed	ω	s-1		n = 400 min <sup>-1</sup> $\omega = \frac{2 \cdot \pi \cdot 400}{60}$ $\omega = 41,89 \text{ s}^{-1}$
Cutting speed	٧ <sub>c</sub>	m/min	$v_{c} = \frac{d \cdot \omega}{33.3}$ $v_{c} = \frac{d \cdot \pi \cdot n}{1000}$	n = 400 min <sup>-1</sup> , d = 20 mm v <sub>c</sub> = $\frac{20 \cdot \pi \cdot 400}{1000}$ v <sub>c</sub> = 25,133 m/min
Feed per revolution	f	mm		
Feed speed	Vf	mm/min	$v_f = f \cdot n$	$      n = 400 \text{ min}^{-1} \\       f = 0,800 \text{ mm} \\       v_f = 0,800 \cdot 400 \\       v_f = 320 \text{ mm/min} $
Force	F	N	$\mathbf{F} = \mathbf{k}_{c} \cdot \mathbf{A}$	
Torque	м	Nm	$M = \frac{F \cdot d}{2000}$	F = 200 N, d = 20 mm M = $\frac{200 \cdot 20}{2000}$ M = 2 Nm
Mechanical work	W	J	$W = F \cdot U$	F = 200 N, d = 20 mm U = $\frac{d \cdot \pi}{1000}$ = 0,063 m W = 200 \cdot 0,063 = 12,6 J
Performance	Ρ	W	$P = \frac{F \cdot v_c}{60}$ $P = M \cdot \omega$	$ \begin{array}{ll} F &= 200 \; \text{N}, \; v_{c} = 25,133 \; \text{m/min} \\ P &= 83,78 \; \text{W} \\ M &= 2 \; \text{Nm}, \; \; \omega = 41,89 \; \text{s}^{-1} \\ P &= 83,78 \; \text{W} \\ \end{array} $
Efficiency	η	-	$\eta = \frac{P_{ab}}{P_{an}}$ $\eta < 1$	$P_{ab} = 58,65, P_{an} = 83,78 W$ $\eta = \frac{58,65}{83,78} = 0,7$


 $\pi = 3,141592654$ d = Diameter in mm U = circumference in m 1 kW = 1,36 PS 1 PS = 0,736 kW m min m

$$1 \frac{1}{s} = 60 - \frac{1}{mir}$$

1/s = 60/min = 1 Hz  
1J = 1 Nm = 1 
$$\frac{\text{kg} \cdot \text{m}^2}{\text{s}^2}$$
  
1W = 1  $\frac{\text{J}}{\text{s}}$  = 1  $\frac{\text{Nm}}{\text{s}}$  = 1  $\frac{\text{kg} \cdot \text{m}^2}{\text{s}^3}$ 

М	MF	G (BSP)	UNC	UNF	UNS	UNEF	8 UN	12 UN	BSW	BSF	TR	NPT NPTF	NPS NPSM	RC RP	BA	w	PG	FG BSC	RD RMS	Camera (Tripod)	VG	Tools	Techn. Information

## **Round Dies Geometries**



b

α

β

۷

rake angle

spiral angle

chamfer angle

diameter of hole for fixing screw

- D outside diameter
- E thickness
- a width of tooth
- c width of notch

#### Preparation of workpiece:

- concentrical chamfer ease entry of cutting
- workpiece diameter must be less than the nominal diameter

#### Chamfer

- Standard chamfer (length, see at the item)
- Spiral entry: free flow of chips ahead of the die and a reducing of cutting torque.
- This result in an improved surface finish on the cut threads and longer die life
- 70° (short chamfer) chamfer length: 1,25 pitch = 70°

### **Tolerances for Round Dies**

Metric ISO thread acc. DIN 13 - coarse and fine thread

4h = tolerance class "fine"

6h = tolerance class "middle", for small diameters (up to M 1,4)

6g = tolerance class "middle" - Standard

6e = undersize tolerance; for bolts that receive a surface treatment or a galvanizing (layer thickness up to 8 μm). Cutting dies with 6e tolerance are cutting about 0,03 mm smaller than normal cutting dies with 6g tolerance.

8e = undersize tolerance; for bolts that receive a strong surface coating (layer thickness about 16 - 18 µm)

Unified thread UNC, UNF, UNEF, UNS, UN, UNJC, UNJF etc.

3A = tolerance "fine"

- 2A = standard tolerance "middle"
- 1A = tolerance "coarse"

Whitworth pipe thread G (BSP) acc. DIN-ISO 228

- A = standard tolerance "middle"
- B = tolerance "coarse"

Μ	MF	G	UNC	UNF	UNS	UNEF	8	12	BSW	BSF	TR	NPT	NPS	RC	BA	w	PG	FG	RD	MINI	Camera	VG	Tools	Techn.
		(BSP)					UN	UN				NPTF	NPSM	RP				BSC	RMS		(Tripod)			Informatio



### **Cutting speeds for Machine Forming Taps**

materials	tensile strength	forming speed in m/min	recommended lubrication
construction steels, free-macining steels, cold-extrusion steels etc.	< 600 N/mm²	20 - 80	Cutting oil/ Emulsion
construction steels, heat-treatable steels, cast steels etc.	< 800 N/mm²	20 - 60	Cutting oil/ Emulsion
heat-treatable steels, cold-extrusion steels, nitriding steels etc.	< 1000 N/mm²	10 - 40	Cutting oil
corrosion and acid proof steels ferritic, martensitic	< 950 N/mm²	10 - 25 (with emulsion just limitedly applicable)	Cutting oil
corrosion and acid proof steels austenitic	< 950 N/mm²	10 - 25 (with emulsion just limitedly applicable)	Cutting oil
aluminium wrought alloys	< 550 N/mm²	15 - 40	Cutting oil/ Emulsion
aluminium cast alloys	Si < 12%	15 - 40	Cutting oil/ Emulsion
pure copper	< 400 N/mm²	20 - 40	Cutting oil/ Emulsion
copper-zinc alloys (brass long-chipping)	< 550 N/mm²	40 - 80	Emulsion

forming (cutting) speed [m/min] = (diameter \*  $\pi$  \* number of rotation) / 1000 number of rotation n [1/min] = (cutting speed in m/min \* 1000) / (diameter \*  $\pi$ ) feed programming [mm/min] = number of rotation \* pitch Please notice that the mentioned cutting speeds are only for orientation. The right cutting speed is depend on lubrication and application.



 BAER Vertriebs GmbH

 Robert-Bosch-Str. 5

 68542 Heddesheim

 Germany

 Tel:
 +49 (0) 6203 4048 790

 Fax:
 +49 (0) 6203 4048 791

 E-Mail: info@gewindebohrer.de

 www.threading-tools.com

150

М	MF	G	UNC	UNF	UNS	UNEF	8	12	BSW	BSF	TR	NPT	NPS	RC	BA	w	PG	FG	RD	MINI Camera	VG	Tools	Techn.
		(BSP)					UN	UN				NPTF	NPSM	RP				BSC	RMS	(Tripod)			Information